

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emred.state.nm.us/ocd/joistrict.iii/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-2018 Operator Rin API #30-0 45-09408				
Property Name Viceson Well No. Location: Unit Section 19 Township 30 Range 13				
Well Status(Shut-In or Producing) Initial PSI: Tubing 102 Intermediate 1/2 Casing 138 Bradenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
Testing BI	Bradeni	PRESSU head Csg	RE INTERM Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min		138		Steady Flow
10 min		138		Surges
15 min		138		Down to Nothing
20 min				Nothing
25 min_				Gas
30 min				Gas & Water
				Water
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE  REMARKS:				
REMARKS.				
By Witness_				
(Position)				
E-mail address				