



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distrct.htm](http://emnr.state.nm.us/ocd/District%20III/3distrct.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-20-2018 Operator Rina API #30-0 45-34616

Property Name Reya Well No. #25 Location: Unit 0 Section 20 Township 30 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 8 Intermediate N/A Casing 8 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		8		
10 min	0		8		
15 min	0		8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

B-H blew down in 3 seconds
No After flow.

By

Daryl Wright
Lease operator
(Position)

Witness

E-mail address

NMOC
MAY 04 2018
DISTRICT III

NMOC
MAY 04 2018
DISTRICT III