



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 5-31-2018 Operator Hilcorp Energy Co. API # 30-039-23910

Property Name San Juan 27-5 Unit Well # 108E Location: Unit Sec 15 Twn 27 Rge 5

Land Type:

State _____
Federal _____
Private _____
Indian _____

NMOCD

MAY 31 2018

DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well ☒ Post Workover

TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 565 psi. for 30 mins. Test passed/failed

REMARKS: Pressured up to approx 565psi. Holding at 565psi at 15 min. Held at approx 560 for last 10 min of test. Had very slight drop of 5psi at about 20 min.

Unable to perform BH test as BH was open upon arrival

212P 3800' - Drilled out to CIP

1hr clock 1hr clock 1000# last Cal. 4/13/18

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

On-site Supervisor
(Position)

Revised 02-11-02