



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 11 2018

DISTRICT III

Date of Test 6/11/2018 Operator Hilcorp Energy API #30-045-06023

Property Name Huerfano Unit Well No. 87 Location: Unit K Section 1 Township 26 Range 9

Well Status (Shut-In) or Producing Initial PSI: Tubing 64 Intermediate NA Casing 87 Bradenhead 3.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	2.5		91		
10 min	1.5		92		
15 min	1.0		92		
20 min	1.0		93		
25 min	1.5		93		
30 min	1.5		94		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR X BLACK X

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3.0 INTERMEDIATE NA

REMARKS:

Well Shut in during test. BH flowed water immediately, initially water was black, changed to clear in 30 sec, 4 gal 1st 5 min, 3.75 gal 2nd 5 min, 3.5 gal 3rd 5 min, 4th 3.5 gal, 5th 3.5 gal, 6th 3.5 gal. light sulfur odor on water, water sample collected

By Roger J. Lane
Operator III
(Position)

Witness Joseph P. Kelly

E-mail address _____