



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

NMOC

JUN 11 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 6/11/2018 Operator Hilcorp Energy API #30-045-11677

Property Name Navajo C Well No. 2 Location: Unit L Section 31 Township 27 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 110 Intermediate NA Casing 110 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		110		
10 min	0		111		
15 min	0		111		
20 min	0		112		
25 min	0		112		
30 min	0		112		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges	X	
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE NA

REMARKS:

Well shut in for test. BH through 1", water flowed in surges, collected water sample. Water overall greyish color. Produced 1 gallon of water during 30 min test

By [Signature]
Operator ITT
(Position)

Witness [Signature]

E-mail address _____