



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/5/18 Operator Redwolf Prod. API #30-0 45-22634

Property Name Delo Well No. 12 Location: Unit K Section 26 Township 25 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate N/A Casing 23 Bradenhead 0
PSIG PSIG

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	23	0	23
10 min	0	0	23	0	23
15 min	0	0	23	0	23
20 min	X				
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	EST REPORT ✓	✓
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0

INTERMEDIATE 0
BRADENHEAD INTERMEDIATE

REMARKS:

By Bruce C. Delo

Witness _____

(Position)

E-mail address _____

JUN 11 2018

DISTRICT III