



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

JUN 04 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III
Date of Test 5-23-18 Operator Coleman Oil & Gas #30-0 45-29429
Property Name Steward Cam Well No. #1 Location: Unit P Section 28 Township 32N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate N/A Casing 102 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>102</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>102</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>102</u>		
20 min	<u>0</u>		<u>Shut-In Pressure</u>		
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>yes</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

nothing on Braden Head watch & Record pressure
for 15 min Stop Test Shut-In Braden Head Record pressure
After 5 min 0 PSI

By Drew Zager Witness _____

PRODUCTION FOREMAN / LEASE OPERATOR
(Position)

E-mail address dlf5@earthlink.net