



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 28-JUNE-2018 Operator HILLTOP API # 30-0 39-21807

Property Name SAN JUAN 31-6 Well # 30 Location: Unit A Sec 35 Twn 31 Rge 6

and Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Using Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Casinghead Pres. _____ Tbg. Inj. Pres. _____
Leak-off Pres. _____
Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000 PSI SPRING, 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 500 PSI AND
PRESSURE HELD FOR THE ENTIRE TEST

by EJZHA
(Operator Representative)

Witness [Signature]
(NMOCD)

LEAD OPERATOR
(Position)

NMOCD

JUN 29 2018

Revised 02-11-02

DISTRICT III