



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

NMOC

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170
<http://emr.state.nm.us/ocd/district111/3distric.htm>

NMOC

JUN 18 2018

DISTRICT III

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 5-8-18 Operator Southland Royalty Company, LLC API # 3004509315

Property Name MCCORD 013 Location: Unit N Section 22 Township 30 Range 13
(Well Name and Number)

Well Status(Shut-in or Producing) Initial PSI: Tubing 162 Intermediate N/A Casing 168 Bradenhead 72

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing

Time
5 minutes
10 minutes
15 minutes
20 minutes
25 minutes
30 minutes
5 minute SI

PRESSURE - Bradenhead

BH Blowdown	Casing Monitor	Intermediate Monitor
0	174	
2	175	
4	176	
6	177	
7	178	
7	181	
2	182	

PRESSURE - Intern

Intermediate Blowdown	Casing Monitor

FLOW CHARACTERISTICS

	Bradenhead Flowed	Intermediate Flowed
Steady Flow	☒	
Surges		
Down to Nothing		
No Flow		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 2 Intermediate N/A

REMARKS:

Blowing to Lite Blow 15 min / 2 blew down to nothing 2 minutes
Blew to Atmosphere in Casing 168, 170, 173 Casing Built up!!

By Vandon Pratt + Vandon Pratt
Lease Operator

Witness _____

(Position)

NMOC Test Area: B

1

E-mail address jhampton@ctfieldsvc.com