



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

JUL 12 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-12-18 Operator Jason Norton Green API #30-0 45-21847
Property Name La Plata Well No. 2 Location: Unit 1 Section 30 Township 32 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate Casing 26 Bradenhead 26

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>28</u>		<u>28</u>		
10 min	<u>29</u>		<u>29</u>		
15 min	<u>30</u>		<u>30</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u>✓</u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 32

INTERMEDIATE N/A

REMARKS:

Steady flow - followed casing
90 days to fix or plug need for analysis
By Joan Medrano Witness Monica Kuehling

(Position)

E-mail address