



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 15 Aug 2018 Operator HILCORP API #30-0 39 30047

Property Name SAN JUAN 295 Well No. 2313 Location: Unit B Section 16 Township 29 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	570	0	520
10 min	0	0	560	0	520
15 min	0	0	550	0	520
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT

By Craig Ward
Consultant
(Position)

Witness [Signature]

MMOCD

E-mail address cward87401@gmail.com

Aug 16 2018

DISTRICT III