



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-8-18 Operator DSR Operating LLC API #30-0 4505528
Property Name Central Dist. 1st. W. 57 Well No. 57 Location: Unit 5 Section 5 Township 25 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate 1/4 Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>22</u>		
10 min	<u>0</u>		<u>20</u>		
15 min	<u>0</u>		<u>18</u>		
20 min	<u>0</u>		<u>16</u>		
25 min	<u>0</u>		<u>15</u>		
30 min	<u>0</u>		<u>14</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/4

REMARKS:

Nothing when opened - Nothing
when opened after 5 min shut in
90 days fix or plug -

By Jacob Harter
Jacob Harter
(Position)

Witness Monica Truckling

E-mail address jharter@cottonwoodconsulting.com