



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

NMOC

AUG 10 2018

DISTRICT III

Date of Test 8/8/2018 Operator Roddy Production Co. API #30-045-08274

Property Name Ransom Well No. 1 Location: Unit I Section 13 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 3 Intermediate 0 Casing 12 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>12</u>	<u>0</u>	<u>13</u>
10 min	<u>0</u>		<u>13</u>	<u>0</u>	<u>19</u>
15 min	<u>0</u>		<u>13</u>	<u>0</u>	<u>16</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>X</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Plunger well, plunger cycled during intermediate test.

By Jeremy Divine

Witness _____

Foreman

(Position)

E-mail address jdivine@crowquest.com