



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-8-18 Operator DSR Prod. LLC API #30-0 45-25871
Property Name Central Bist. Unit Well No. 96 Location: Unit 16 Section 16 Township 25 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 4 Intermediate N/A Casing 49 Bradenhead 26

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>48</u>		
10 min	<u>0</u>		<u>48</u>		
15 min	<u>0</u>		<u>48</u>		
20 min	<u>0</u>		<u>48</u>		
25 min	<u>0</u>		<u>48</u>		
30 min	<u>0</u>		<u>48</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Had blow to vapors in 30 seconds.
Vapors at 5-10-15-20-25-30. Bleed whole 30 min.
Gas Samples taken BH tubing Prof. Casing

By Jacob Harter
Jacob Harter
(Position)

Witness Monica Lucking

E-mail address jharter@cottonwoodconsulting