



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10 AUG 2018 Operator DJR API #30-0 45-32447

Property Name CARSON WDH Well No. 242 Location: Unit Section 24 Township 25 Range 2

Well Status(Shut-In or Producing) Initial PSI: Tubing -5 Intermediate N/A Casing -3 Bradenhead .2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME	<u>0</u>	<u>N/A</u>	<u>-3</u>		
5 min	<u>0</u>	<u> </u>	<u>-3</u>		
10 min	<u>0</u>	<u> </u>	<u>-3</u>		
15 min	<u>0</u>	<u> </u>	<u>-3</u>	<u>N/A</u>	
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		<u>N/A</u>
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT PUFFED TO NOTHING

By Jacob Harter

Witness John Durkin

(Position)

E-mail address jharter@cotlunaconsulting.com

NMCD

AUG 10 2018

DISTRICT III