



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

DISTRICT III

AUG 08 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-7-18 Operator Manalix Dist. LLC API #30-0 45-33464
Property Name Century Point SW Well No. 1 Location: Unit 1 Section 24 Township 31 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 940 Intermediate 0 Casing 620 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	620	0	620
10 min	0	0	620	0	620
15 min	0	0	620	0	620
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		✓
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Duff when opened. Into nothing when opened. Nothing when opened after 5 min shut in. Nothing when opened after 5 min shut in.

By A. R. O'Neil
Bradenhead
(Position)

Witness Monica Kiedling

E-mail address _____