



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10 AUG 2018 Operator DJR API #30-0 45-33944

Property Name BISTI GALLUP 242 Well No. 2 Location: Unit 20 Section 20 Township 25 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 58 Intermediate N/A Casing 59 Bradenhead 124

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	58		
10 min	0		58		
15 min	0		58		
20 min	0		58		
25 min	0		58		
30 min	0		58		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT FLOWED FOR THE ENTIRE TEST.

RELEASED AGAS ANALYSIS, AND WELL BORE SCHEMATIC

By Jacob Harter

Witness JM

Jacob Harter
(Position)

E-mail address jharter@cottonwoodconsulting.com

NMCOO

AUG 10 2018

DISTRICT III