NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

NMOCD
AUG 29 2018
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-28-18 Operator HilCorp API #30-0 45-26657

Property Name Huerfano Unit Well No. 181E Location: Unit ___ Section 26 Township 26 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 124 Intermediate N/A Casing 127 Bradenhead 119

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	2		134		
10 min	0		134		
15 min	0		134		
20 min	0		135		
25 min	0		135		
30 min	0		135		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	/	
Surges		
Down to Nothing		
Nothing		
Gas	/	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 15 INTERMEDIATE N/A

REMARKS: Hard puff to vapors in 3 seconds. Blew for whole 30 minute test. Gas samples taken - BH - Casing - tubing

By [signature] Witness Monica Kuehling

MSO
(Position)

E-mail address _____