



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOCD

AUG 28 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 8/28/2018 Operator Hilcorp API #30-0 45-34728
Property Name McLard Well No. 16 Location: Unit F Section 15 Township 30 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 132 Intermediate NA Casing 134 Bradenhead 114

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	17		135		
10 min	9		136		
15 min	8		136		
20 min	7		137		
25 min	7		121		
30 min	6		112		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 41

INTERMEDIATE NA

REMARKS:

BA through 1" valve, blew hard for 10 min, then moderate blow for rest of test
Well cycled @ 25 min into test. Requested gas analysis on BH, Csg and Prod.
strings and updated well bore schematic.

By Pete Jim
MSO
(Position)

Witness Jonathan D. Kelly

E-mail address _____