NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

NMOCD
SEP 25 2018
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-25-18 Operator Hilcorp Energy Co. API #30-0 45-26112

Property Name McCord Well No. 11E Location: Unit ___ Section 9 Township 30 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 186 Intermediate N/A Casing 206 Bradenhead 185

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		208		
10 min	0		211		
15 min	0		211		
20 min	0		213		
25 min	0		214		
30 min	0		215		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE N/A

REMARKS: Med-to light blow in 20 seconds - fumes at 8 minutes - fumes for rest of 30 minute test leak test still applies.

By Pete Jim Witness Monica Kuehling

Field operator
(Position)

E-mail address _____