OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM. 87410 (505) 334-6178 FAX: (505) 334-6170 http://cronrd.state.nm.us/ocd/DistrictIII/3distrig.htm

BRADENHEAD TEST REPORT

(Submit I copy to above address)

Date of Test	st Aug. 22 2018 Operator M&C Drilling Company							API #30-0 45-32486							
Property Name						Location: Unit					28N	Range	11W		
Well Status (Shut-	n or roducing		Initial PSI	Tubing	0	Intermediate	Nane	Casing	148	_ Bradenhead		0			
	OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH														
PRESSURES:									FLOW CHARACTERISTICS						
TESTING	Bra BH IN	denhead T Csg	INT Int	TERM Csg				BRADENHEAD			INTERMEDIATE				
TIME 5 minutes	0	148				Steady Flow									
10 minutes	0	148				Surges									
15 minutes	0	148				Down to Nothin	a.			J-101					
20 minutes	0 1.78					Nothing	g		1						
						Nothing									
25 minutes		-			-	Gas		-			-				
30 minutes						Gas & Water									
						Water									
If bradenhead flowed water, check all of the descriptions that apply below:															
CLEAR FRESH SALTY SULFUR BLACK															
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE															
REMARKS:															
Start test 6:42 pm - 7:02 pm															
	_/	1	,					uos							
The state of the s															
By Namel Witness_															
_		(Position)		-										
E-mail address								NMOCD							
								SEP 2 4 2018							
								DISTRICT III							