OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX; (505) 334-6170

http://emnrd.state.nm.us/ocd/District/III/3distric.htm

DISTRICT III

## BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	Aug. 20 2018 Operator M&G Drilli						іпд Сотряцу АРП				#30-0 45-32646			
Property Name							_Location; Unit					27N Rang	ge 08W	
Well Status (Shut-In	ow roducin						Intermediate							
						_B_/_				3244				
	OPEN	BRAI	ENHEAD	AND INT	ERMEDIA	те то	ATMOSPHERE	INDIVI	DUALLY	FOR 1	MINUTES	EACH		
	PRESSURES:								FLOW CHARACTERISTICS					
TESTING	Bradenhead INTERM						BRADENHEAD						SEDIATE	
TIME	ВН	INT	Csg	Int	Csg	7		•	BRADE	NHEAD		INTERN	TEDIATE	
5 minutes	0		360		ļ	_	Steady Flow				-		~	
10 minutes	0		360			4	Surges							
15 minutes	0		360				Down to Nothin	g			y v vonantimo de la companya de la c			
20 minutes						Nothing								
25 minutes							Gas							
30 minutes							Gas & Water							
											<u> </u>			
Water														
If bradenhead flowed water, check all of the descriptions that apply below:														
CLEAR FRESH SALTY SULFUR BLACK														
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE														
Start test 1:42 pm - 2:02 pm														
By Nam / Shame Witness														
(Position) E-mail address														
NMOCD														
								2 ~ 2018						
SEP 2 - 2018														