

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 15 2018
FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **SF-078388**
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well
 Oil Well Gas Well Other

7. If Unit of CA/Agreement, Name and/or No.
Huerfanito Unit

2. Name of Operator
Hilcorp Energy Company

8. Well Name and No.
Huerfanito Unit 67

3a. Address
382 Road 3100, Aztec, NM 87410

3b. Phone No. (include area code)
505-599-3400

9. API Well No.
30-045-05905

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Surface Unit O (SWSE), 990' FSL & 1550' FEL, Sec . 12, T26N, R09W

10. Field and Pool or Exploratory Area
Ballard Pictured Cliffs

11. Country or Parish, State
San Juan , New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other FAN
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 1/14/2016. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 1/10/2018 with Bob Switzer. Please remove this well from the Hilcorp Energy Company bond.

NMCOB
SEP 27 2018
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Kandis Roland

Title **Operations/Regulatory Technician**

Signature *Kandis Roland* Date **8/14/2018**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *Suzanne N. Frost* Title *Supv NRS* Date *9/9/18*

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office *FR*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RCC Reclamation Completion			Location Name: <u>HUELENNITO 67</u>			Date: <u>12-18-2017</u>			Revision 2 (3/7/17)		
API#: <u>30-045-05905</u>			UL-Sec-Twn-Rng: <u>0 T26N R9W Sec 12</u>			Lat/Long: <u>36.49791, -107.75689</u>					
Surface Owner: <u>BLM</u>			Lease#: <u>SF-078388</u>			County/State: <u>SAN JUAN NM</u>					
Pipeline Owner: <u>ENTER PRIZE</u>			Twin/Co-Locate Well Name & Operator: <u>N/A</u>								
Onsite: <u>Sam Jaeger</u>			Agency Inspector: <u>Bob Smith</u>			Contractor:			Seed Mix:		
Interim Reclamation			Final Reclamation			Remediation					
Completed	Incomplete	N/A	Completed	Incomplete	N/A	Completed	Incomplete	N/A	Completed	Incomplete	N/A
			3rd party pipeline removed	✓		Facilities stripped					
			Anchors removed	✓		Certificate of waste issued & approved					
			Equipment and piping removed	✓		Depth:					
			Power poles removed		✓	Width:					
			Cathodic protection removed		✓	Length:					
			Vegetative cages removed		✓	Date of Excavation Start:					
			CMP's removed		✓	Date of Excavation End:					
			Non native gravel buried or removed	✓		Date of Backfill Start:					
			Noxious weeds removed or sprayed	✓		Date of Backfill End:					
			Invasive weeds removed or sprayed	✓		Yards Hauled Out:					
			Contouring complete	✓		Impacted Soil Hauled To:					
			Top soil spread	✓		Yards Hauled In:					
			Diversions clean and functional	✓		Fresh Soil Hauled In From:					
			Silt trap clean and functional	✓		Approval to backfill					
			Cattle guard / gates removed		✓	Back fill mechanically compacted					
			Cellar / mouse hole covered	✓		Facilities reset					
			Erosion under control	✓		Trash and debris removed					
			Location properly ripped	✓		Close Out Completed					
			Location properly disked	✓		Soil Removal Sundry Ready to be Filed					
			Location seeded	✓							
			Photo transect installed		✓						
			Access road properly closed	✓							
			Public use controlled	✓							
			Barriers in place	✓							
			Grazing controlled	✓							
			P&A marker installed & legible	✓							
			Well sign removed	✓							
			Growth at least 70%	✓	✓						
			Trash and debris removed from location	✓							
			Final reclamation photos taken	✓							
			Agency Inspection Date: <u>1-10-2018</u>	✓							
			FAN Ready to be filed	✓							
Comments:			Comments:			Comments:					
			NEEDS SILT TRAPS Complete 12-28-2017								
			POST FINAL INSPECTION								