



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 09/13/2018 Operator Mustang Resources LLC API #30-045-26003

Property Name Dryden Well No. 01E Location: Unit A Section 28 Township 28N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 149 Intermediate .5 Casing 155 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>.5</u>	<u>156</u>		
10 min	<u>0</u>	<u>.5</u>	<u>158</u>		
15 min	<u>0</u>	<u>.5</u>	<u>160</u>		
20 min				<u>0</u>	<u>163</u>
25 min				<u>0</u>	<u>165</u>
30 min				<u>0</u>	<u>166</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	☒
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Plunger lift well - Completed Test during off cycle
Intermediate has changed > 20% since last Test 2 PSI to .5 PSI
Bradenhead remained the same

By [Signature]
Production Foreman
(Position)

Witness _____

E-mail address djohnson@mustangresourcesllc.com

NOOCD
OCT 01 2018
DISTRICT III