



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

OCT 05 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-5-18 Operator Hilcorp Energy Co API #30-0 45-30812

Property Name Salty Dog SW Well No. 2 Location: Unit J Section 5 Township 29 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 1268 Intermediate NA Casing -1 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		-1		
10 min	0		-1		
15 min	0		-1		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: light blow to dead end 4 seconds through 1/4"
Valve - nothing when opened after 5 min shut in
Max 1280/1100

By Fred Rector
SWD Operator
(Position)

Witness Monica Kuehling

E-mail address _____