NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

DISTRICT III
OCT 12 2018
NMOCD

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-11-18 Operator Hilcorp Energy Co API #30-0 39-24549

Property Name San Juan 31-6 Unit SWD Well No. 301 Location: Unit ___ Section 6 Township 30 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 1386 Intermediate 1 Casing 0 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	1	0	0	0
10 min	0	1	0	0	0
15 min	0	1	0	0	0
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Puff to dead in 1 second. Puff when opened after 5 min shut in. Int. Medium blow to dead at 5 min. K:11 1575. Nothing when opened after 5 min shut in

By [signature] Witness Monica Kuehling

SWD Operator (Position) Lucas Lucas O.K bpt O.K

E-mail address _____