



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

DISTRICT III

OCT 12 2018

DOWN

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-11-18 Operator Hilcorp Energy API #30-0 39-24807
Property Name San Juan 29641 SW Well No. 301 Location: Unit 2 Section 29 Township 29 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 1132 Intermediate 15 Casing -5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	14	-5	0	-5
10 min	0	15	-5	0	-5
15 min	0	15	-5	0	-5
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BA Long puff to dead at 15 seconds - nothing
when opened after 5 min shut-in Int - light
flow 5-10 - to dead at 15 minutes - puff when opened
By Fred Rector Kill 1800 Witness Monica Cushing after 5 min
SDN Operator (Position) Shut-in

E-mail address _____