



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

OCT 13 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

Date of Test 10-12-18 Operator Hilcorp Energy Co. API #30-0 45-27935
Property Name San Juan 32-8 (4 SW 1/4) Well No. 301 Location: Unit 16 Section 16 Township 31 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 2121 Intermediate 0 Casing -2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	-2	0	-2
10 min	0	0	-2	0	-2
15 min	0	0	-2	0	-2
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		/
Nothing	/	
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Nothing when opened - Nothing when opened after 5 min shut in. Int light blow to clear at 10 seconds. Nothing when opened after 15 min

By Fred Lester
SWD Operator
(Position)

Witness Monica Cuchling Shutin.

E-mail address _____