



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT
NMOC

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OCT 13 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.12.18 Operator Hilcorp Energy Co API #30-0 45 28549
Property Name Sun Juan 32-7th SW Well No. 301 Location: Unit Section 34 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 581 Intermediate 1 Casing 0 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	0	0	0
10 min	0	1	0	0	0
15 min	0	1	0	0	0
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH - long puff when opened. Nothing when
opened after 5 min shut in. Int. Mud blow to
(2:36 minutes) clear - Nothing when opened after 5 min
shut in
By Paul Richter Witness Monica Cuello
SWD Operator (Position)

E-mail address