

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

382 Road 3100, Aztec, NM 87410

3b. Phone No. (include area code)

505-599-3400

5. Lease Serial No.

SF-078566-A

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

HOWELL 100

9. API Well No.

3004533876

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit N (SESW), 1040' FSL & 1630' FWL, Sec. 34, T028N, R008W

10. Field and Pool or Exploratory Area

BASIN FC/BLANCO P. C. SOUTH

11. Country or Parish, State

SAN JUAN, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Interim Reclamation

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company conducted a legacy interim reclamation inspection on 9/13/2018 with BLM Inspector Roger Herrera and received approval for the reclamation BMPs on the subject well.

NMOCB

OCT 22 2018

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kandis Roland

Title **Operations/Regulatory Technician - Sr.**

Signature

Kandis Roland

Date **10/2/2018**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Superior

Title

Superior

Date

10/11/18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.


Office

FFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCB

RCC Reclamation Completion				Location Name: HOWELL 100		Date: Revision 3 (3/21/17)								
API#: 3004533876		UL-Sec-Twn-Rng: N 34 028N 008W		Lat/Long: 36.61391, -107.67106 NAD 27										
Surface Owner:		Lease#: SF-078566-A		County/State: SAN JUAN, NM										
Pipeline Owner: ENT		Twin/Co-Locate Well Name & Operator:												
Onsite: Dale Crawford		Agency Inspector: 		Contractor:		Seed Mix:								
Interim Reclamation		Completed	Incomplete	N/A	Final Reclamation		Completed	Incomplete	N/A	Remediation		Completed	Incomplete	N/A
Have pit sample results been approved					3rd party pipeline removed					Facilities stripped				
Has water been removed from pit					Anchors removed					Certificate of waste issued & approved				
Have pit marker photos been taken					Equipment and piping removed					Depth:				
Has certificate of waste been issued & approved					Power poles removed					Width:				
Have all pit contents been removed					Cathodic protection removed					Length:				
Has sample after content removal been taken					Vegetative cages removed					Date of Excavation Start:				
Is location contoured					CMP's removed					Date of Excavation End:				
Is there 4' of cover over pit					Non native gravel buried or removed					Date of Backfill Start:				
Has top soil been spread evenly					Noxious weeds removed or sprayed					Date of Backfill End:				
Has all non-native gravel been buried or removed					Invasive weeds removed or sprayed					Yards Hauled Out:				
Has pit liner been removed					Contouring complete					Impacted Soil Hauled To:				
Has all trash been removed					Top soil spread					Yards Hauled In:				
Have all weeds been removed					Diversion clean and functional					Fresh Soil Hauled in From:				
Teardrop allows vehicle access to all facilities					Silt trap clean and functional					Approval to backfill				
Drainage ditches allow adequate run off					Cattle guard / gates removed					Back fill mechanically compacted				
All non-traffic areas disked properly					Cellar / mouse hole covered					Facilities reset				
All non-traffic areas seeded					Erosion under control					Trash and debris removed				
Seeded areas have been mulched					Location properly ripped					Close Out Completed				
Noxious weeds have been removed or sprayed					Location properly disked					Soil Removal Sundry Ready to be Filed				
Invasive weeds have been removed or sprayed					Location seeded									
Barriers set to deter traffic					Photo transect installed									
Silt traps are functional					Access road properly closed									
Culverts are functional					Public use controlled									
Upper diversion is functional					Barriers in place									
Erosion under control					Grazing controlled									
Photo transect installed					P&A marker installed & legible									
Have wellhead cages and jersey barriers been removed					Well sign removed									
Have reclamation pictures been taken					Growth at least 70%									
Growth at least 70%					Trash and debris removed from location									
Agency Inspection Date: 9/13/18					Final reclamation photos taken									
Sundry is ready to file					Agency Inspection Date:									
					FAN Ready to be filed									
Comments:				Comments:				Comments:						