



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-18-18 Operator Enduring Resources API # 30-045-35554

Property Name Chaco 2308-6H Well No. 396H Location: Unit H Section 6 Township 23 Range 8

Well Status (Shut In or Producing) Initial PSI: Tubing 49 Intermediate 0 Casing 578 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>555</u>	<u>-</u>	<u>572</u>
10 min	<u>0</u>	<u>0</u>	<u>562</u>	<u>-</u>	<u>564</u>
15 min	<u>0</u>	<u>0</u>	<u>555</u>	<u>-</u>	<u>563</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OCT 18 2018
DISTRICT III

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing on intermediate when opened - nothing after five minute shut in.

Nothing on BH when opened-

By Preston Clements
Emissions Tech
(Position)

Witness [Signature] NMOC

E-mail address _____