



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III3district.htm](http://emnr.d.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/16/18 Operator Enduring Resources API #30-0 45-35731

Property Name Lybrook 2307-34B Well No. 765 Location: Unit 3 Section 34 Township 23 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate X Casing 270 Bradenhead X

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	<u>Ø</u>	<u>X</u>	<u>270</u>		
5 min	<u>Ø</u>	<u>X</u>	<u>270</u>		
10 min	<u>Ø</u>	<u>X</u>	<u>270</u>		
15 min	<u>Ø</u>	<u>X</u>	<u>270</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE X

REMARKS:

Well is disconnected.

By Preston Chmura

Witness

Emissions Tech

(Position)

E-mail address pchmura@enduringresources.com

NMOC

OCT 23 2018

DISTRICT III

10/18/18