



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-31-18 Operator Mata Corp's Posa LLC API # 30-0 45-21470

Property Name Madrigal Post Well # 1 Location: Unit C Sec 26 Twn 25 Rge 11

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒ _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOCD
OCT 31 2018
DISTRICT III

Temporarily Abandoned Well (Y/N): Yes TA Expires: 10-31-2023

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. 1/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 570 psi. for 35 mins. Test passed/failed

REMARKS:

Leak. Dropped to 540 and held last 10 minutes of
packer set at-
needs Sunday to put in TA status - well inactive
for 10 years

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

