



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

OCT 31 2018

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 10-31-18 Operator Manalix D. Dosa LLC API # 30-0 45-25784

Property Name Trading Post Dosa Well # 2 Location: Unit 0 Sec 23 Twn 25 Rge 11

Land Type:

State _____
Federal _____
Private _____
Indian ✓

Well Type:

Water Injection _____
Salt Water Disposal ✓
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): 0 TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 992

Pressured annulus up to 920 psi. for 30 mins. Test passed/failed 0

REMARKS:

Packer set at 4880
Surf 4962 - 5010 TB-5100
dropped 5 lbs last 10 minutes.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

