



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4/27/06 Operator Mountain States API # 30-0 31-20609


Property Name Hospah Sand Well # 94 Location: Unit ___ Sec 1 Twn 17 Rge 9

Land Type:

State ___
Federal ___
Private ☒
Indian ___

Well Type:

Water Injection ☒
Salt Water Disposal ___
Gas Injection ___
Producing Oil/Gas ___
Pressure observation ___



Temporarily Abandoned Well (Y/N): ___ TA Expires: ___

Casing Pres. 0 Tbg. SI Pres. ___ Max. Inj. Pres. ___
Bradenhead Pres. 0 Tbg. Inj. Pres. ___
Tubing Pres. 0
Int. Casing Pres. ___

Pressured annulus up to 515 psi. for 30 mins. Test passed failed

REMARKS: Bleed off to 500


By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Prod. Supt.
(Position)

Revised 02-11-02

84



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

30-031-20609
CHART NO. MC MP-1000-150F
Mountlake *Gates*
4-27-06

METER *HSA#94*
CHART PUT ON *NR* M
LOCATION *1-17-9*
REMARKS *Monica (Cochling)*

TAKEN OFF M

PRINTED IN U.S.A.