

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 04 2018

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

Farmington Field Office
Bureau of Land Management

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NM-0468128
2. Name of Operator Hilcorp Energy Company		6. If Indian, Allottee or Tribe Name
3a. Address 382 Road 3100, Aztec, NM 87410	3b. Phone No. (include area code) 505-599-3400	7. If Unit of CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit A (NENE), 790' FNL & 790' FEL, Sec. 34, T29N, R13W		8. Well Name and No. Hagood 30
		9. API Well No. 30-045-20979
		10. Field and Pool or Exploratory Area Basin FC/Basin Dakota
		11. Country or Parish, State San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other FAN
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 7/21/10. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and approved by the Land Owner Tommy Bolack on 4/18/18. Please remove this well from the Hilcorp Energy Company bond.

NMOCD
NOV 01 2018
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Kandis Roland		Title Operations/Regulatory Technician
Signature <i>Kandis Roland</i>		Date 10/4/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>Suzanne Scott</i>	Title <i>Supv NRS</i>	Date <i>10/15/18</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <i>FFO</i>	

NMOCD



Final Reclamation Detail and Approval

Date Well P&A'd: July 7, 2010

Well Name: Hagood #30

Location: Unit Letter _____ Footages 790 FNL & 790 FEL

Sec. 34 ; T-29 - N, R - 13 -W; County: San Juan ; State: NM

Surface Owner Name: Tommy Bolack


Reclamation Detail:

Equipment removed: yes no _____
(All wellhead surface equipment, tanks, meter runs, piping (removed or capped and abandoned below ground, as appropriate), cathodic equipment, fencing etc.)

Location and road have been re-contoured: yes no _____

Erosions / Drainage issues addressed with final reclamation: yes no _____

Location seeded according to Surface Owner request: yes no _____

I, , agree the final reclamation on the subject well has been satisfactorily performed.

(Surface Owner Name): B-Square Ranch - Tommy Bolack

(Address): _____

(Date): 4-18-18

Signature: _____

Witness: _____

RCC Reclamation Completion				Location Name: HA 9000 #30			Date: 4-17-2018			Revision 2 (3/7/17)		
API#: 30-045-20979				UL-Sec-Twn-Rng: "A" T29N R13W Sec 34			Lat/Long: 36.68807, -108.18674					
Surface Owner: B SQUARE RANCH				Lease# NM-0468128			County/State: SAN JUAN NEW MEXICO					
Pipeline Owner: ENTERPRISE				Twin/Co-Locate Well Name & Operator:								
Onsite: SAM JACQUEZ			Agency Inspector:			Contractor:			Seed Mix:			
Interim Reclamation				Final Reclamation			Remediation					
Completed	Incomplete	N/A	Completed	Incomplete	N/A	Completed	Incomplete	N/A	Completed	Incomplete	N/A	
			3rd party pipeline removed	✓		Facilities stripped						
			Anchors removed	✓		Certificate of waste issued & approved						
			Equipment and piping removed	✓		Depth:						
			Power poles removed		✓	Width:						
			Cathodic protection removed		✓	Length:						
			Vegetative cages removed	✓		Date of Excavation Start:						
			CMP's removed		✓	Date of Excavation End:						
			Non native gravel buried or removed	✓		Date of Backfill Start:						
			Noxious weeds removed or sprayed	✓		Date of Backfill End:						
			Invasive weeds removed or sprayed	✓		Yards Hauled Out:						
			Contouring complete	✓		Impacted Soil Hauled To:						
			Top soil spread	✓		Yards Hauled In:						
			Diversions clean and functional	✓		Fresh Soil Hauled In From:						
			Silt trap clean and functional	✓		Approval to backfill						
			Cattle guard / gates removed	✓		Back fill mechanically compacted						
			Cellar / mouse hole covered	✓	✓	Facilities reset						
			Erosion under control	✓		Trash and debris removed						
			Location properly ripped	✓		Close Out Completed						
			Location properly disked	✓		Soil Removal Sundry Ready to be Filed						
			Location seeded	✓								
			Photo transect installed		✓							
			Access road properly closed	✓								
			Public use controlled	✓								
			Barriers in place	✓								
			Grazing controlled	✓								
			P&A marker installed & legible	✓								
			Well sign removed	✓								
			Growth at least 70%	✓								
			Trash and debris removed from location	✓								
			Final reclamation photos taken	✓								
			Agency Inspection Date: 4-17-2018	✓								
			FAN Ready to be filed	✓								
Comments:				Comments: SUBMIT FAN FIELD VISIT WITH Tommy BOLACK						Comments:		