



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 3-16-06 Operator ROBERT L. BAYLESS, PRODUCER, LLC API #30-0 45-28993

Property Name MOSELEY Well No. 1 Location: Unit K Section 2 Township 30N Range 12W

Well Status (Shut-In or Producing) Tubing 190 Intermediate — Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME | PRESSURES: | | | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
|------------|------------|--------------|-----------|----------------------|------------------------|
| | BRADENHEAD | INTERMEDIATE | CASING | | |
| 5 minutes | <u>0</u> | <u>—</u> | <u>22</u> | Steady Flow | |
| 10 minutes | <u>0</u> | <u>—</u> | <u>22</u> | Surges | |
| 15 minutes | <u>0</u> | <u>—</u> | <u>22</u> | Down to Nothing | |
| 20 minutes | | | | Nothing <u>X</u> | |
| 25 minutes | | | | Gas | |
| 30 minutes | | | | Gas & Water | |
| | | | | Water | |


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Checked braden head, had no pressure



By B. Sandy Andrade

Witness —

Pumper
(Position)

E-mail address —