



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-4-06 Operator ROBERT L. BAYLESS, PRODUCER, LLC API #30-0 45-29505

Property Name FLOYD Well No. 2 Location: Unit P Section 7 Township 30N Range 12W

Well Status (Shut-In or Producing) Tubing 200 Intermediate - Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>-</u>	<u>40</u>	Steady Flow	
10 minutes	<u>0</u>	<u>-</u>	<u>40</u>	Surges	
15 minutes	<u>0</u>	<u>-</u>	<u>40</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Checked bradenhead, had no pressure



By Brandy Aranda

Witness

Pumper
(Position)

E-mail address