



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-11-06 Operator ROBERT L. BAYLESS, PRODUCER, LLC API #30-0 45-30024

Property Name KRAUSE Well No. 1 Location: Unit C Section 2 Township 26N Range 11W

Well Status (Shut-In or Producing) Tubing 150 Intermediate Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>5</u>	Steady Flow	
10 minutes	<u>6</u>		<u>5</u>	Surges	
15 minutes	<u>0</u>		<u>5</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>5</u>	Nothing <u>X</u>	
25 minutes	<u>0</u>		<u>5</u>	Gas	
30 minutes	<u>0</u>		<u>5</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:



By BS

Witness

Sample
(Position)