

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

(Sublint 1	copy to above address)
Date of Test 10-76-18 Operator	Maralex API #30-045-24047
Property Name Taxe Ted 7:27:13 Well No.#3	Location: Unit Section 7 Township 27 Range 13
Well Status Shut-In or Producing) Initial PSI: Tubing 37 Intermediate NA Casing 37 Bradenhead O	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
Testing Bradenhead INTERM BH Int Csg Int Csg TIME	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
5 min 0 37 10 min 0 37	Steady Flow
15 min 0 37	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE NA	
REMARKS: BH through 1= fittings, No pressure	
By Crau W	Vitness
(Position)	
E-mail address	NMOCB
	DEC 1 0 2018