



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distr.htm](http://emnr.state.nm.us/ocd/District%20III/3distr.htm)

NMOCB

06 2018

DIST III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12/5/18 Operator Enduring Resources API #30-0 45 - 24925

Property Name Campbell Corn Well No. 1E Location: Unit D Section 15 Township 27 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 105 Intermediate X Casing 113 Bradenhead 34

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	Bradenhead					
	BH	Int	Csg	Int	Csg	
TIME						
5 min	☒	X	115			
10 min	☒	X	115			
15 min	☒	X	116			
20 min	☒	X	116			
25 min	☒	X	117			
30 min	☒	X	117			

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	☒	
Surges	☒	
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	☒	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☒

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2 INTERMEDIATE X

REMARKS:

At the open of the bradenhead there was a steady flow of water for less than 1 min and was reading 34. Throughout the remainder of the test the bradenhead surged ever now and then. At the 5 min shut in the bradenhead built 2 lbs and at the open it flowed water steadily for a few seconds.

By Preston Clemmons

Witness ☒

Emissions Tech
(Position)

E-mail address p.clemmons@enduringresources.com

Water sample taken 12/5 per James.
Results should be back in approx 1 week.
will submit then. Sep

12/6/18