



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/26/18 Operator Advanced Wireless Communications, LLC API # 30-045-29573
Property Name Panther Well No. 1 Location: Unit Section 25 Township 30N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>✓</u>	<u>6</u>		
10 min	<u>0</u>	<u>✓</u>	<u>6</u>		
15 min	<u>0</u>	<u>✓</u>	<u>6</u>		
20 min	<u>0</u>	<u>✓</u>	<u>6</u>		
25 min	<u>0</u>	<u>✓</u>	<u>6</u>		
30 min	<u>0</u>	<u>✓</u>	<u>6</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Slight puff then down to nothing.

By Kristen Moore
Operator
(Position)

Witness ✓

E-mail address Kristen@advancedwirelessllc.com

NMOCD
NOV 28 2018
DISTRICT III