



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.25.18 Operator Maralex API #30-0 45-30125

Property Name Trading Post 23 Well No. 2 Location: Unit Section 23 Township 25N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate NA Casing 26 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		26		
10 min	0		26		
15 min	0		26		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BH through 1" Fittings, nothing.

By Eric Crum
Mechanic
(Position)

Witness ✓

E-mail address

NMOCD

DEC 10 2018

DISTRICT III