NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-25-18 Operator Maralex API #30-045-34418

Property Name Trading Post 26 Well No. 2R Location: Unit ___ Section 26 Township 25N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate NA Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead		INTERM	
	BH	Int	Csg	Int	Csg
TIME 5 min	0		32		
10 min	0		32		
15 min	0		32		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: BH through 1" Fittings, light puff.

By Eric Crain

Mechanic
(Position)

Witness ✓

E-mail address ____

NOV 10 2018
DISTRICT III