



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

NMOCD

FEB 01 2019

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1-31-19 Operator Dugan Production API # 30-0 45-26460

Property Name Mary Lou Well # 1 Location: Unit A Sec 32 Twn 24 Rge 10

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): 0 TA Expires: _____

Casing Pres. _____
Bradenhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 1004

Pressured annulus up to 425 psi. for 30 mins. Test passed/failed

REMARKS:

Dacker 3355

top of well 3458
bottom 3570

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

55

60 0

5

50

NMOCB

FEB 01 2019

DISTRICT III

45

10

Graphic Controls

CHART NO.

Wuganad.
MC MP-1000-1HR
A-32-2410

METER

CHART PUT ON

TAKEN OFF

LOCATION

Mary Lou #1 S4D

REMARKS

MIT
1/31/19

40

15

30-045-26460
M. G. K. K. K. K. K.
Superior
1-31-19

James H. H.

PRINTED IN U.S.A.