



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT
(TA OR UIC)

Date of Test 15-FEB-2019 Operator DJR API # 30-0 45-34002

Property Name BISTI GALLUP 20 Well # 9 Location: Unit ___ Sec ___ Twn ___ Rge ___

Land Type:

State ___
Federal ___
Private ___
Indian ___

Well Type:

Water Injection ___
Salt Water Disposal ___
Gas Injection ___
Producing Oil/Gas ___
Pressure observation ___

Temporarily Abandoned Well (Y/N): ___ TA Expires: ___

Casing Pres. ___ Tbg. SI Pres. ___ Max. Inj. Pres. ___
Cradenhead Pres. ___ Tbg. Inj. Pres. ___
Tubing Pres. ___
Int. Casing Pres. ___

Pressured annulus up to ___ psi. for ___ mins. Test passed/failed

REMARKS: 1000 PSI SPRING 60 MINUTE LOCK

THE CASING WAS PRESSURED UP TO 1020 PSI AND PRESSURE
FELL TO 600 AND HELD FOR THE LAST 15 MINUTES

BHT'S NEED TO BE DONE IN 30 DAYS, 6 MONTHS, AND 1 YEAR.

by Jesus F. Carmona
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

NMOCD

FEB 15 2019

DISTRICT III

Revised 02-11-02