



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

MAR 12 2019

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-12-19 Operator DJR Oper API # 30-0 45-27101

Property Name Sunny Corbett Well # 2 Location: Unit I Sec 31 Twp 25 Rge 11

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: 3-12-2024

Casing Pres. 0.5 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 32
Int. Casing Pres. 7/11

Pressured annulus up to 600 psi. for 30 mins. Test passed/failed

REMARKS:

Leak at 4746-4756 Cemented in 2014
CIBT 3098
Last test bleed at 10 lbs during 5 min
2nd test dropped to 578. Deliverable -

By Ten Duggen Witness Monica Kuchling
(Operator Representative) (NMOCD)

(Position)

Revised 02-11-02

