



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

APR 15 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-19 Operator Hilary Energy Co. API #30-0 39-25341
Property Name San Juan 58-7 Ut Well No. 31A Location: Unit Section 20 Township 28 Range 7
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 72 Intermediate 0 Casing 73 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	73	0	72
10 min	0	0	73	0	73
15 min	0	0	73	0	73
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Nothing when opened. Nothing when opened
after 5 min shut in. Int. Blew to dead at 4 seconds.
Well started producing shut-in to 72 psi. Nothing
By Mark Goodwin Witness Monica Quintero
Nothing when opened after
5 min shut in

(Position)

E-mail address