



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3district.htm](http://emrdd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-27-19 Operator DJRO Purling LLC API #30-0 45-33944
Property Name Bist. Gallup Well No. 2 Location: Unit 2 Section 20 Township 35 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate N/A Casing 0 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Down to nothing in 2 seconds - No thing when
opened after 5 min shut in - this is 30th day
test - 1 month & 1 year required.

By Tom Dezzie

Witness Monica Luchini

(Position)

E-mail address _____