



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 23 APRIL 2019 Operator HIL CORP API #30-0 45-33236

Property Name ALLISON UNIT Well No. 1345 Location: Unit 6 Section 8 Township 32 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 50 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	0	N/A	540		
5 min	0		575		
10 min	0		570		
15 min	0		540	N/A	
20 min	0		540		
25 min	0		540		
30 min	0		540		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	N/A
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW
DOWN TO NOTHING IN 5 SECONDS

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

NMOCD

APR 23 2019

DISTRICT III